



SSM 52787 2017-2020 F-150 And 2017-2019 F-Super Duty - Not Completing Transmission Characterization/Solenoid IDN Procedure Using IDS

Some 2017-2020 F-150 and 2017-2019 F-Super Duty vehicles may not successfully complete the Transmission Characterization/Solenoid IDN procedure using the Integrated Diagnostic System (IDS) scan tool. This may be due to the IDS not being at the latest software level. To correct this condition, update the IDS to the latest software level prior to running the transmission strategy download procedure.