



**Bulletin No.:** PIP5991

**Published date:** 06/24/2024

## Preliminary Information

### PIP5991 6.6 L5P Diesel Soot Concerns After EGR Valve Replacement

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN:</b> from to	<b>Engine:</b>	<b>Transmissions:</b>
Chevrolet Silverado	2500HD/3500HD	2017 - 2023	All	All 6.6 L5P	All
GMC	Sierra 2500HD/3500HD	2017 - 2023	All	All 6.6 L5P	All

<b>Involved Region or Country:</b>	<b>North America</b>
<b>Condition:</b>	<b>Excessive soot accumulation after exhaust gas recirculation (EGR) valve replacement. Possible DTCs P24A4, P2459 and/or P2463.</b>
<b>Cause:</b>	<b>Check vehicle history to see if this vehicle had an EGR valve replacement from Jan 2023 to June 2024 and part number 12713478 was installed.</b>

#### Correction:

Check the electronic parts catalog (EPC) for the correct part number EGR valve.

#### Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>06/24/2024 - Created on.</b>

 GM Global Brands

© 2024 General Motors. All Rights Reserved.