



Bulletin No.: PIT6190

Published date: 06/25/2024

Preliminary Information

PIT6190 Turn Signal Flashes Opposite Direction After Cancel

Models

Brand:	Model:	Model Years:	VIN: from	VIN: to	Engine:	Transmissions:
Chevrolet	Colorado	2023 - 2024	All	All	All	All
GMC	Canyon	2023 - 2024	All	All	All	All

Involved Region or Country:	North America
Condition:	Turn signal will flash opposite side or signal lane change after cancel. This usually flashes left after a right turn cancel.
Cause:	Software issue.

Engineering is aware of this condition and is working towards a fix. This PI will be updated when a remedy is available.

Version History

Version	1
Modified	06/25/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.