

WORK DESCRIPTION FOR FIELD MEASURE

Code: 24P2095002

Version: 2.0


Replace reinforcement sheet metal for radiator crossmember

Model 236

Work procedure

1. Replace reinforcement sheet metal for radiator crossmember (8).

 For basic information, see AR62.30-P-2300WEB.



Parts

Quantity	Designation	Part no.
1 *	Reinforcement sheet metal for radiator crossmember	A 236 620 18 00

* **The required replacement parts for the equipment variant must be determined according to the vehicle identification number (VIN) via the XENTRY Parts Information system.**

 Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
12-2193	Operations: Replace reinforcement sheet metal for radiator crossmember Includes: Disconnect/connect ground line of 12 V on-board electrical system battery, remove/install front bumper	2.0 h	20 950 02
12-2194	Operations: Extra work for: Replace reinforcement sheet metal for radiator crossmember in vehicles with PARKTRONIC system (code 235).	0.1 h	20 950 02
12-2195	Operations: Extra work for: Replace reinforcement sheet metal for radiator crossmember in vehicles with 360-degree camera (code 501).	0.1 h	20 950 02
12-2196	Operations: Extra work for: Replace reinforcement sheet metal for radiator crossmember in vehicles with Pedestrian protection (code U60).	0.3 h	20 950 02
12-2201	Operations: Extra work for: Replace reinforcement sheet metal for radiator crossmember in vehicles with DISTRONIC PRO (code 239).	0.2 h	20 950 02

Mercedes-Benz