



STAR ONLINE PUBLICATION




Case Number: S2408000095

Release Date: August 2024

Symptom/Vehicle Issue: Check Engine Lamp (CEL) On

Customer Complaint /Technician Observation: The owner complains the CEL is on and the engine is running rough. The technician observed the Powertrain Control Module (PCM) has set P0158-02 O2 Sensor 2/2 Circuit High.

Repair Procedure: Inspect the black 4-way O2 Sensor component connector for any signs of a Terminal Pushed Out (TPO) and/ or a connector not latched. Insert any loose or pushed out circuits, use the push, pull, push to latch, and secure the connector. Test the operation to complete pg 1 and 2.




Pg 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.



STAR ONLINE PUBLICATION



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.