



SIB 46 04 24
SERVICE SOLUTION: Rattling Fairing Side Panel

MODEL

Model	Model Description
K83	F 900 R
K84	F 900 XR

SITUATION

Rattling of the rear side panels caused by play in the push fit connections.

PROCEDURE

Apply a felt strip in these locations to reduce this play.



**PARTS
INFORMATI
ON**

Part Number

62 10 6 974 904	Felt strip
-----------------	------------

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf 46 04 24 SESO Rattling Fairing Side Panel.pdf](#)

