



SSM 52799 2024 F-150 - DTC U211B:87 Setting In The HCM When A Diagnostic Self-Test Is Performed

Some 2024 F-150 vehicles may exhibit diagnostic trouble code (DTC) U211B:87 in the headlamp control module (HCM) when a diagnostic self-test is performed. This may be due to the software contained within the HCM. To correct the condition, reprogram the HCM to the latest software level using the Ford Diagnosis and Repair System (FDRS) scan tool. Replacement of the HCM will not resolve this condition. For claiming, use causal part 13K198 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.