



SSM 52811 2023 F-Super Duty - 6.7L - Inaccurate Intelligent Oil Life Monitor Reading Zero Percent Oil Life

Some 2023 F-Super Duty vehicles equipped with a 6.7L engine may exhibit an inaccurate intelligent oil life monitor reading zero percent oil life after 1000 miles (1609 km) under normal vehicle usage due to the software in the instrument panel cluster (IPC). This condition does not affect vehicle durability and no additional diagnosis or service is required for this condition at this time. Refer to the Owner's Manual for proper oil change intervals and inform customers that they can continue to drive the vehicle. Engineering is currently working on a solution for this condition that is expected in December 2024. Replacement or reprogramming of the IPC will not currently resolve this condition. Monitor OASIS for additional information and schedule service appointments for customers once the repair becomes available.