



SSM 52823 2025 Aviator - Tire Vibration From Temporary Flat Spotting - Built On 15-May-2024 And Through 15-Aug-2024

Some 2025 Aviator vehicles built on 15-May-2024 and through 15-Aug-2024 may exhibit a vehicle vibration felt at 35-80 mph (55-130 km/h) in the steering wheel and/or seat. This may be due to tire flat spotting caused by vehicles being held awaiting delivery. Tire flat spotting may be a temporary concern that is resolved, with no repairs required, after the customer drives a minimum of 200 miles (320 km). Refer to Workshop Manual, Section 204-4A if diagnosis or repair is required after the vehicle has been driven this minimal distance.