



## **SSM 52826 2020-2024 Aviator - HUD Does Not Allow The Projection Height To Be Adjusted**

Some 2020-2024 Aviator vehicles equipped with a head-up display (HUD) may exhibit a condition where the display does not allow the projection height to be adjusted. This may be due to the software in the HUD. To correct this condition, reprogram the HUD using the latest software level of the Ford Diagnosis and Repair System (FDRS) diagnostic tool. For claiming, use causal part 19G468 and applicable labor operation in Section 10 of the Service Labor Time Standards (SLTS) Manual.