

Technical Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



Subject: POWER LIFTGATE REAR BCM WARNING BEEP IS TOO LOW	Bulletin No.: 09-040/24
	Last Issued : 08/21/2024

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2024 CX-90 (with power liftgate) with VINS lower than JM3KK*****134335 (produced before September 9, 2023)

DESCRIPTION

Some customers may complain that the 2 mph rear BCM power liftgate (PLG) warning beep is too low, making it difficult to notice that the PLG is not closed properly with the front instrument panel warning lights. As the vehicle speeds up to above 6 mph, the front BCM warning beep will activate to notify the driver that the PLG may not be properly closed due to interference from rear cargo items. This is caused by the warning beep volume on the rear BCM being set too low. To eliminate this concern, the PLG control module has been modified.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify the customer concern.
2. Replace the power liftgate control module with the modified one according to the instructions on MGSS (POWER LIFTGATE (PLG) CONTROL MODULE REMOVAL/INSTALLATION).
3. Verify the repair.

PARTS INFORMATION

Parts Number	Description	Qty.
KMV7-62-6H0K	Control Unit, Power Liftgate	1

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION**NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	61
Damage Code	9W
Part Number Main Cause	K***-62-6H0*
Quantity	1
Operation Number / Labor Hours:	XXWRZERX / 0.4 Hrs. (PHEV) XXWRZFRX / 0.5 Hrs. (H3T inline 6)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.