



Date: 29.08.2024

Model: All Emira 4-Cylinder Models

Number: TSB-131-24024

Copy files should be maintained by:

Service Manager		Service Reception		Supervisor		Parts Manager	
-----------------	--	-------------------	--	------------	--	---------------	--

TITLE

Important information for a temporary recovery procedure for the Central Powertrain Controller (CPC Module).

REASON


Updated software was recently released for the CPC module, but because of reported failures to complete the programming successfully when trying to upload the software, which had left some vehicles immobile* and CPC recovery cannot be achieved without performing a CPC RELOAD, therefore this update option has been temporarily disabled.

*Because the CPC module in a partially programmed state cannot operate or communicate correctly with the vehicle networks.

ACTION

It is expected to re-enable this feature soon, but once enabled, if there is a failure to complete the programming successfully during an upgrade, please contact Emira Support (detailing on an LCMS ticket that this request requires LTIL Emira Support assistance).

Emira support will then guide you through a remote session on the CPC RELOAD procedure.



CHARGES

No charges are associated with the contents of this bulletin.

Ends