

 Preview Solution CBR-2364-4

Battery Electric Vehicle (BEV) DTC P108664 - Charging Switch Unit B, Voltage Supply, Signal Plausibility Failure

Published 20 August 2024

Valid For

Volvo VNR-E and Mack LR-E Model years 2021 to current

Solution

If charging cannot be completed due to active DTC P108664, follow the instructions below:

1. Using Premium Tech Tool (PTT), update HPCU software to latest version.
2. Verify that the code is inactive and the vehicle is able to charge.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article