

## FRONT END ACCESSORY DRIVE MALFUNCTION – 3.0L / P6

### Customer Voice:

- Electrical system fault on instrument cluster or noise from engine.

### Technical Description:

- Possible accessory drive belt tensioner and belt have become damaged.

### Status:

- With the engine running safely, and without risking causing any damage, record a video of any abnormal noises coming from the front-end accessory drive belt area and submit the video with an EPQR.
- The EPQR must make reference to PTS\_100.
- Retain all removed parts. Engineering will contact your Retailer to organize collection of the parts for Engineering analysis

Refer to SSM 76143 / SSM 76144

#### Range Rover

- 20-24MY Range Rover
- 19-24MY RR Sport
- 21-24MY RR Velar

#### Defender

- 20-23MY Defender

#### Discovery

- 21-24MY Discovery

#### Jaguar

- 17-24MY F-PACE

