

## MALFUNCTION INDICATOR LAMP(MIL) ON WITH DIAGNOSTIC TROUBLE CODE P0080-88

### Customer Voice:

- MIL lamp on the instrument cluster

### Technical Description:

- DTC P0080-88 stored in the Transmission Control Module (TCM).
- A software error has been found that will not have any effect on vehicle operation.

### Status:

- Update the TCM to the latest available level with TOPIx Cloud.

### Range Rover

- 24MY Range Rover- NC11 ONLY
- 24MY RR Sport – NC11 ONLY



Refer to SSM 76150