

SERVICE ACTION N870 – SINGLE SPEED TRANSFER CASE FRONT OUTPUT SHAFT FLANGE

OWNER NOTIFIED PROGRAM - N870 – SINGLE SPEED TRANSFER CASE FRONT OUTPUT SHAFT FLANGE

AFFECTED MODELS	24MY Range Rover Sport SV Variants ONLY
VOLUME AFFECTED	301 US 58 CAN
REPAIR	A potential concern has been identified where the front output shaft flange of the single speed transfer case may not be correctly installed. To make sure there is no degradation of performance over time, the front output shaft flange needs to be secure in the transfer case. An inspection of the front output shaft and flange assembly is required. If failed, a new transfer case is needed.
REPAIR TIME	2.4hrs. + DIDO – Inspection only 5.4hrs + DIDO – Inspection + transfer case replacement
CAMPAIGN LAUNCH	Launched on August 7th, 2024
NOTES	Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory which must be repaired before sale and delivery. Sold vehicles must be completed at the next service visit.