



Technical Service Bulletin

39 Whistling noises at about 100 mph from rear final drive / propshaft

39 24 68 2074844/1 August 9, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
S4, S5, S5 Cabriolet, and S5 Sportback	2018 – 2025	All	Not Applicable
RS 5	2018 – 2019 2021 – 2025		
RS 5 Sportback	2019 2021 – 2025		

Condition

Customer statement:

Whistling noises at about 100 (+/- 5) mph from rear final drive/driveshaft.

Workshop findings:

The noises can be traced back to the rear final drive / driveshaft area.

Technical Background 1

Not applicable.

Production Solution

Not applicable.

Service

Check whether a driveshaft with the part number 8W0 521 101 C or 8W0 521 101 K is fitted.

In the event of a complaint, the driveshafts 8W0 521 101 C or 8W0 521 101 K can be replaced with a driveshaft with the following part numbers (depending on availability):

- 8W0 521 101 F



Technical Service Bulletin

or

- 8W0 521 101 L



If a driveshaft with a part number other than 8W0 521 101 C or 8W0 521 101 K is fitted, the TSB must not be performed.

Warranty

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	3902		
Damage Code:	0020		
Labor Operations:	Check driveshaft	3902 0199	20 TU
	If part number matches, remove and install drive shaft	3902 19xx	See SRT with associated operations
Claim Comment:	As per TSB 2074844/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Driveshafts: 8W0 521 101 F or 8W0 521 101 L (depending on availability)

Additional Information

All part and service references provided in this TSB (**2074844**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.



Technical Service Bulletin

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.