



Technical Service Bulletin

72 Folding cover for rear center armrest is loose

72 24 58 2074897/1 August 27, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2019 – 2025	All	Not Applicable
S8	2020 – 2025		
A8 e quattro	2020 – 2021		

Condition

Customer states:

- The folding cover of the rear center armrest is loose.

Workshop findings:

- The brackets for the armrest cover have broken (Figures 1, 2).



Technical Service Bulletin



Figure 1. Broken armrest brackets

Figure 2. Broken armrest brackets

Technical Background 1

Component analyses have clearly shown that the brackets have broken due to external influences.

Production Solution

Not applicable.



Technical Service Bulletin

Service

Claims for replaced parts will not be reimbursed.

Warranty

This damage is due to outside influence and is not covered by any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2074897**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.