



Bulletin No.: PIT6203
Published date: N/A

Preliminary Information

PIT6203 Headlamp Or DRL Flicker Or Flash

Models

Brand: GMC **Model:** Canyon 2024 **Model Years:** All **VIN:** All All **Engine:** All **Transmissions:** All

Involved Region or Country:	North America
Condition:	Intermittent flicker or flash from the headlamp(s) or the DRL(s).
Cause:	Issue internal to the LED controller that is part of the headlamp assembly.

Correction:

The only correction for this concern is to replace the effected headlamp assembly at this time.

If the repair direction changes this PI will be updated.

Version History

Version	1
Modified	07/16/2024 - Created.