

<b>Reference</b>	SSM76156
<b>Models</b>	New Range Rover / L460 New Range Rover Sport / L461
<b>Title</b>	NC11 Engine Noise
<b>Category</b>	Engine
<b>Last modified</b>	12-Aug-2024 00:00:00
<b>Symptom</b>	497000 Engine Noise
<b>Attachments</b>	NC11 - Dynamic engine noise.mp4 (NC11 - Dynamic engine noise.mp4) NC11 - Stationary engine noise.MOV (NC11 - Stationary engine noise.MOV)

<b>Content</b>	<p><b><u>Model / Model Year / Derivative</u></b></p> <p>Range Rover / 23MY onwards / V8 4.4L NC11 Petrol Range Rover Sport / 23MY onwards / V8 4.4L NC11 Petrol</p> <p><b><u>Situation:</u></b></p> <p>An engine whining noise can be heard from within the passenger compartment which increases and decreases with engine speed. The noise is most noticeable on engine overrun while driving, or when increasing engine speed in PARK or NEUTRAL. See 'Attachment 1' and 'Attachment 2' example videos.</p> <p><b><u>Cause:</u></b></p> <p>Suspected engine oil cooler hose clash.</p> <p><b><u>Action:</u></b></p> <p>Do not renew any components for this concern. Record a video of the whining noise from within the passenger compartment. Raise a Technical Assistance (TA) directed to PTS_100 for further assistance and attach the video recording to the TA.</p> <p>(Ref 00CCR2057)</p>
----------------	--

anBhdhRlcnM7MjAyNC0wOS0wNiQxODoxNj0NS45MDRaOzE2NS4yMjUuOS42MTs=