

Reference	SSM76172
Models	New Range Rover / L460 New Range Rover Sport / L461
Title	Malfunction Indicator Lamp (MIL) on with Diagnostic Trouble Code (DTC) U0080-88 stored
Category	Driveability
Last modified	28-Aug-2024 00:00:00
Symptom	698298 Malfunction Indicator Lamp
Content	<p>Range Rover / 24MY / NC11 Only Range Rover Sport / 24MY / NC11 Only</p> <p>Situation:</p> <p>JLR Engineering investigations have found that certain vehicles are exhibiting both of the below symptoms:</p> <p>Intermittent MIL on Instrument Cluster Panel (IPC) DTC U0080-88 stored in the Transmission Control Module (TCM). Note: This causes no physical effect on vehicle operation.</p> <p>Cause:</p> <p>Software error.</p> <p>Action:</p> <p>Refer to the service information below.</p> <p>SERVICE INFORMATION:</p> <p>Update the TCM to the latest available level with TOPIx Cloud.</p> <p>(Ref 000383275)</p> <p><small>anBhdHRlcnM7MjAyNC0vOS0wNiQxNjoxMzowNC4xMjhaOzE2NS4yMjUuOS42MTs=</small></p>