



**Bulletin No.:** PIT6203A  
**Published date:** 07/30/2024

## Preliminary Information

### PIT6203A Headlamp Or DRL Flicker Or Flash

#### Models

**Brand:** GMC   **Model:** Canyon 2024   **Model Years:** All   **VIN:** All All   **Engine:** All   **Transmissions:** All

<b>Involved Region or Country:</b>	North America
<b>Condition:</b>	Intermittent flicker or flash from the headlamp(s) or the DRL(s).
<b>Cause:</b>	Issue internal to the LED controller that is part of the headlamp assembly.

Engineering is aware of this concern and is working towards a resolution. It is no longer recommended to replace the headlamp assemblies as it has been found that the issue is present in the replacements currently stocked at CCA. This PI will be updated when this direction changes.

#### Version History

<b>Version</b>	2.0
<b>Modified</b>	07/16/2024 - Created on. 07/30/2024 - Removed replacement recommendation.