

<b>REFERENCE:</b>	<b>TSB:</b> 21-036-24 REV. A <b>GROUP:</b> 21 - Transmission and Transfer Case	<b>Date:</b>	September 5, 2024	<b>REVISION:</b>	21-036-24
<b>VEHICLES AFFECTED:</b>	<b>2024 (GG) Dodge Hornet</b> This bulletin applies to vehicles built on or before <b>March 21, 2024 (MDH 0321XX)</b> equipped with a <b>2.0L I4 DOHC DI Turbo Engine w/ESS (Sales Code EC1)</b> and <b>9-Speed 948TE FWD/AWD Auto Trans (Sales Code DFH)</b> .	<b>MARKET APPLICABILITY:</b>			
		<input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH			
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may experience:</b> <ul style="list-style-type: none"> <li>Shift paddles will not work when the shifter is in Drive. Shift paddles only work when the transmission is in manual mode.</li> </ul>				
<b>CAUSE:</b>	TCM software				

**This bulletin supersedes Technical Service Bulletin (TSB) 21-036-24, date of issue May 21, 2024, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include a Note and converting the TSB to an Information Only bulletin.**

**DISCUSSION:**

**NOTE: **\*\*This service action is no longer in effect. Please follow published service procedures in Service Library to diagnose and repair the vehicle.\*\*****

**POLICY:**

**\*\*Information Only.\*\***

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*