

**Technical Service Bulletin (TSB)**  
**Bubbles On Rear Door Panel**

<b>REFERENCE:</b>	<b>TSB:</b> 23-049-24 REV. A <b>GROUP:</b> 23 - Body	<b>Date:</b>	September 6, 2024	<b>REVISION:</b>	23-049-24
<b>VEHICLES AFFECTED:</b>	<b>**2023** - 2024 (BV) Jeep Renegade</b> This bulletin applies to vehicles built on or after May 06, 2024 (MDH 0506XX) and on or before June 23, 2024 (MDH 0623XX).			<b>MARKET APPLICABILITY:</b>	
				<input type="checkbox"/> NA	<input checked="" type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input checked="" type="checkbox"/> EE	<input type="checkbox"/> CH
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may experience the following:</b>				
	<ul style="list-style-type: none"> <li>• Appearance of bubbles on the rear door panel located in the armrest <a href="#">Fig. 1</a>.</li> </ul>				
<b>CAUSE:</b>	Detachment of the PVC				

This bulletin supersedes Technical Service Bulletin (TSB) 23-049-24, date of issue August 27, 2024, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include an additional model year.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 24-120, date of issue August 27, 2024. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.



**Fig. 1**  
Bubbles On Armrest

**REPAIR SUMMARY:**

This bulletin involves replacing the left rear door panel.

## CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-20-22-9B	Left Rear Door Panel – Replace (0 - Introduction)	6 - Electrical and Body Systems	0.4 Hrs.
Failure Code	ZZ	Service Action	

## SPARE PARTS:

Qty	Part No.	Description	Notes
1	7RM19LXHAA - NA 735784478 - EMEA	Panel-Rear Door Trim	Left Rear Door Panel

## DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

**This RSU only applies to vehicles on the RSU VIN list.**

## REPAIR PROCEDURE:

1. Replace the left rear door panel. Refer to the detailed service procedures available in DealerCONNECT/ Service Library under: Service Info >23 - Body / Doors - Rear / Panel, Rear Door Trim / Removal and Installation.

## POLICY:

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*