



Bulletin No.: PIP5995
Published date: 08/15/2024

Preliminary Information

PIP5995 P04DB Crankcase Ventilation System Disconnected

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Silverado 2500HD/3500HD	2025	All	All 6.6 L5P	All
GMC	Sierra 2500HD/3500HD	2025	All	All 6.6 L5P	All

Involvement Region or Country:	North America
Condition:	A Check Engine Light (CEL) light may come on, especially when towing heavy loads.
Cause:	A dealer technician may find DTC P04DB (Crankcase Ventilation System Disconnected)

Correction:

No action at this time.

Engineering is aware of the issue and is working to release a calibration update to the engine control module.

Do not replace the CCP (Crankcase Pressure Sensor) for this concern.

Version History

Version	1
Modified	8/14/2024 - Created.