



Bulletin No.: PIT6222

Published date: 08/21/2024

Preliminary Information

PIT6222 Ticking Or Clicking Noise Coming From The Rear HVAC

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Cadillac	Escalade	2023 - 2024	All	All	All
Chevrolet	Suburban	2023 - 2024	All	All	All
Chevrolet	Tahoe	2023 - 2024	All	All	All
GMC	Yukon	2023 - 2024	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment that there is a clicking/ticking type noise coming from the rear of the vehicle.
Cause	This concern may be caused by the rear mode door binding where it passes through the rear HVAC case.

Correction:

- 1. Gain access to the rear HVAC mode actuator and remove from the case.**
- 2. Try and move the mode door by hand. The door should move freely with no binding feel at all.**

If there is any binding in the mode door the rear HVAC case will need to be replaced.

Version History

Version	1
Modified	08/21/2024 - Created on.