



Bulletin No.: PIT6227

Published date: 08/26/2024

Preliminary Information

PIT6227 Service Occupant Motion Detection System Message Displayed At Times

Models

Brand:	Model:	Model Years:	VIN:	Engine:	Transmissions:
Chevrolet Equinox EV 2024			from to		
			All All All		All

Involved Region or Country	North America
Condition	Service Occupant Monitor System displayed on Instrument Panel Cluster.
Cause	Body Control Module has an incorrect calibration for the application.

Correction:

If a vehicle is found to intermittently display a "Service Occupant Monitor System" message on the dash please contact TCSC, advise them of the concern and they will issue a VCI to address the issue.

Version History

Version	1
Modified	08/26/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.