



**Bulletin No.:** PIP5990A  
**Published date:** 08/26/2024

## Preliminary Information

### PIP5990A 2.7 L3B Service Engine Part Restriction Has Ended

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Cadillac	CT4-V	2020 - 2022	All	All 2.7 L3B	All
Chevrolet	Silverado 1500	2019 - 2022	All	All 2.7 L3B	All
GMC	Sierra 1500	2019 - 2022	All	All 2.7 L3B	All

<b>Involved Region or Country:</b>	<b>North America</b>
<b>Condition:</b>	<b>2.7 L3B Service Engine Part Restriction Has Ended</b>
<b>Cause:</b>	<b>Limited Stock</b>

#### Correction

General Motors Technical Assistance Center part restriction on 2.7L L3B engine has ended.

We would like to thank all dealers who participated in this restriction for their cooperation.

This engine can now be ordered through the regular GM CCA parts process or PQC process for required dealers (Canada).

Use the vehicle identification number (VIN), SI, and the GM Electronic Parts Catalog to determine the correct part to order.

#### Version History

<b>Version</b>	<b>2</b>
<b>Modified</b>	<b>06/14/2024 - Created. 08/26/2024 - Updated to end restriction.</b>



GM Global Brands  
 © 2024 General Motors. All Rights Reserved.