Individual functions in gesture recognition system is no longer available

Topic number LI82.85-P-078303

Version

Function group 82.85 - Navigation and Communication systems

Date 9/10/24

Validity Vehicles with code 77B or 78B

Reason for change

Complaint

Individual functions such as sliding sunroof or roller sunblind can no longer be operated using the gesture recognition system.

Cause

Gesture recognition system control unit software N168

Remedy

For vehicles before modification year 23/2:

A remedy is currently being developed. Replacing parts will have no effect.

For vehicles as of modification year 23/2:

Considered to be a series production configuration. A change will not be possible in future.

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect

XENTRY Tips

is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Sympton	ns				
Body > Roof system > Tilting/sliding sunroof system > Does not close					
Body > Ro	oof system > Tilting/sliding sunro	of system > Does not of	open		
Communication/information > Entertainment > Overall system/operation > Miscellaneous					
Body > In	erior equipment > Switches, inte	rior, general > Malfund	ction		
Operation	on numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note	