



SSM 52887 2025 Police Interceptor Utility - Perimeter Alert System Fault Message In The IPC And One-Touch Up Front Power Window(s) Inoperative

Some 2025 Police Interceptor Utility vehicles may exhibit a perimeter alert system fault message in the instrument panel cluster (IPC) and one-touch up front power window(s) inoperative. This may be due to a loss of front window initialization. To correct this condition, follow the Workshop Manual (WSM), Section 501-11 > General Procedures > Power Door Window Initialization. Complete initialization, turn off vehicle, remove key and lock vehicle, then wait at least 15 minutes. If the symptoms return, proceed with normal WSM diagnostics.