

**Technical Service Bulletin (TSB)**  
**Fuel Tank Leaking**

<b>REFERENCE:</b>	<b>TSB:</b> 14-006-24 <b>GROUP:</b> 14 - Fuel System	<b>Date:</b>	September 18, 2024	<b>REVISION:</b>	—
<b>VEHICLES AFFECTED:</b>	<b>2024 - 2025 (B1) Jeep Renegade</b> This bulletin applies to vehicles built on or after May 30, 2024 (MDH 0530XX) and on or before July 24, 2024 (MDH 0724XX) equipped with a 1.3L I4 Turbo MAIR DI Engine (Sales Code EYH).			<b>MARKET APPLICABILITY:</b>	
				<input type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input checked="" type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may experience the following:</b>				
	<ul style="list-style-type: none"> <li>A fuel leak (leakage at the fuel tank inlet).</li> </ul>				
<b>CAUSE:</b>	Welding misalignment				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 24-130, date of issue XXXXX XX, 2024. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
14-60-01-9M	Fuel Tank - Replace (2 - Skilled)	14 - Fuel System	1.0 Hrs.
Failure Code	ZZ	Service Action	

**SPARE PARTS:**

Qty	Part No.	Description	Notes
1	68725989AA - Mopar 7096914 - SA	Tank, Fuel	Service Kit

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

## REPAIR PROCEDURE:

1. Replace the fuel tank. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info>1040A10 - Reservatorio de combustivel - remocao/recolocacao e transferencia de combustivel incluso procedimentos necessarios.

## POLICY:

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*