



SSM 52914 2021-2023 F-150 - Raptor/Tremor - DTC U023A:08 After Steering Column Control Module (SCCM) Reprogramming

Some 2021-2023 F-150 Raptor/Tremor vehicles may exhibit diagnostic trouble code (DTC) U023A:08 after reprogramming the SCCM. This DTC does not affect vehicle durability and no additional diagnosis or service is required for this condition at this time. Inform customers that they can continue to drive the vehicle and engineering is currently working on a solution for this condition that is expected in Q4 2024. Replacement or reprogramming of the SCCM or image processing module A (IPMA) will not resolve this condition. Monitor OASIS for additional information and schedule service appointments for customers once the repair becomes available.