



SSM 52918 2024 Bronco - Soft Top Roof - Headliner Detaching From The Soft Top Material

Some 2024 Bronco vehicles equipped with a factory soft top roof may exhibit a headliner that is detaching from the soft top material. This may be due to a lack of adhesive material applied to the headliner during production. To correct this condition, replace the soft top canopy. Do not attempt to reattach the headliner. For claiming use the causal part number 7852700 and claim M-time.