



SSM 52926 2024 Mustang - Dark Horse™ - Manual Transmission - Illuminated MIL With DTCs P0300, P0302 And P0308 Stored In The Powertrain Control Module (PCM)

Some 2024 Mustang Dark Horse™ vehicles equipped with a manual transmission may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble codes (DTCs) P0300, P0302 and P0308 stored in the powertrain control module (PCM) from extended high speed or racetrack operation (driving the vehicle and allowing the engine to hit maximum engine speed, several times and in a short period). This may be due to the software within the PCM. Normal driving conditions will not induce this condition. Component replacement and/or module reprogramming may not correct the concern. Inform customers that they can continue to drive the vehicle and engineering is currently working on a solution for this condition that is expected in January 2025. Monitor OASIS for updates.