



Service Bulletin

Bulletin No.: 24-NA-068

Date: August, 2024

TECHNICAL

Subject: Malfunction Indicator Lamp (MIL) Illuminated – DTC U0672 Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XT5	2020	2024	—	—	2.0L Turbo (LSY)	—
	XT6						
Chevrolet	Blazer						
GMC	Acadia						

Involved Region or Country	North America
Condition	Some customers may comment that the MIL is illuminated. Technicians may find DTC U0672 (Lost Communication with Electric Engine Coolant Pump G59) set.
Cause	This condition may be caused by a mechanical deformation in the fuse.
Correction	Replace the battery distribution fuse block.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Service Procedure

Refer to *Battery Distribution Engine Compartment Fuse Block Replacement*.

Parts Information

Causal Part	Description	Part Number	Qty
X	BLOCK, BAT DISTRIBUTION ENG COMPT FUSE	84922668	1
X		84922669	1
X		85020357	1
X		85020358	1

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4088528*	Battery Distribution Engine Compartment Fuse Block Replacement for DTC U0672 Set	0.5 hr
*This is a unique Labor Operation for bulletin use only.		

Version	1
Modified	Released August 22, 2024

