



GROUP	MODEL
ELE	2024MY Sorento (MQ4a)
NUMBER	DATE
354	September 2024

TECHNICAL SERVICE BULLETIN

SERVICE ACTION: ICU FUSE LABEL REPLACEMENT (SA585)

This bulletin provides information to replace the Integrated Central Control Unit (ICU) fuse label on some 2024MY Sorento (MQ4a) vehicles produced from December 5, 2023 through April 2, 2024. The incorrect ICU fuse label on the affected vehicles was installed. Follow the procedure outlined in this publication to replace the ICU fuse label. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.



NOTICE


A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on KDealer+ (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on KDealer+ (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA585.


Inspection Procedure:

1. Locate the ICU fuse panel cover (A).




2. Remove the ICU fuse label (B).

Note: The 'old' label may **yellow** or **orange**.



3. Install 'new' ICU fuse label (B).

4. Reinstall ICU fuse panel cover (A).




SUBJECT:

ICU FUSE LABEL REPLACEMENT (SA585)**AFFECTED VEHICLE RANGE:**

Model	Production Date Range
Sorento (MQ4a)	December 5, 2023 to April 2, 2024

REQUIRED PART:

Part Name	Part Number	Figure	Qty.
ICU Fuse Label	91990 R5625QQK		1

Note: Order Quantity will be controlled by a UIO% per dealer net submitted warranty claims. No VIN entry will be required. To keep the supply of parts flowing, please be sure to expedite warranty claim filing. As supply becomes more available, the maximum order quantity limit may be increased or removed.

WARRANTY INFORMATION:

N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	84753 R5AAOWK	0	(SA585) Fuse Label Replacement	240A26R0	0.2 M/H	91990 R5625QQK	1

NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference [SA585](#) when accessing the KDealer+ system.