



## SIB 62 01 23 TFT SOFTWARE UPDATE

2024-09-04

This Service Information Bulletin replaces SIB 62 01 23 **dated June 7, 2023**.

### What's New (Specific text highlighted):

- I-Level and ISTA version updated info

## MODEL

Model	Model Description
K53/12	R 1250 R
K54/12	R 1250 RS

The affected vehicles have been marked with campaign number **0062070000** in AIR.

In order to determine if a specific motorcycle is affected by this campaign it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

## SITUATION

With the second model update of the R 1250 R and R 1250 RS, the "Sport" view in the TFT display is part of the standard equipment. This sub-function is not activated in vehicles that are not equipped with optional equipment "224 Drive modes Pro".

This issue will be repaired in Series production August 2023.

## PROCEDURE

Customers with affected vehicles will be notified by a customer letter regarding the missing sport screen view and the option to have it enabled at a later time.


For vehicles that have not yet been delivered, customers must be informed of the missing "Sport" view screen when the vehicle is delivered.

The "Sport" view can be activated with a vehicle software update to I-level K001-23-03-502 in the TFT display available with ISTA version 4.40.3X since the end of March 2023

Note: If any previous warranty claims for defect code 00 62 07 00 00 were rejected or debited after the update was performed to I-Level K001-23-03-502, the dealer can re-submit the warranty claim without requiring another software update. The dealer can also contact warranty using an IDS warranty ticket to appeal the debit.

Overview of "Sport" view

Copyright ©2024 MOTORRAD USA, a division of BMW of North America, LLC. All Rights Reserved



## [CLAIM INFORMATION](#)

Please submit claims via the normal claim process using the information below:

### Defect code

00 62 07 00 00	Enabling the sport screen view
----------------	--------------------------------

### Labor Operation

+61 00 502	Checking the software	2 FRU
61 00 510	Programming control units of vehicle (along with testing software)	2 FRU

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

There is no main labor operation code mapped for this repair. You do not need a main labor operation code to claim this repair.

## [QUESTIONS REGARDING THIS BULLETIN](#)

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

### Supporting Materials

[picture\\_as\\_pdf 62 01 23 TFT UPDATE.pdf](#)

