



STAR ONLINE PUBLICATION



Case Number: S2418000011

Release Date: September 2024

Symptom/Vehicle Issue: Malfunction Indicator Lamp (MIL) Illumination. Diagnostic Trouble Codes (DTCs) U37B8-No Description Available, And P20EE-SCR NOx Catalyst Efficiency Below Threshold, Set.

Discussion: Some customers may experience a MIL illumination. Upon further investigation, the technician may find DTC U37B8 along with DTC P20EE setting in the Powertrain Control Module (PCM). DTC U37B8 will not have a description available for the DTC in wiTECH and there is currently no diagnostic flow chart published for it.

DTC U37B8 is a telltale DTC and is setting due to the P20EE. This is a new DTC, and a diagnostic flow chart is currently being developed. If you receive a vehicle with these DTCs, diagnose and repair the cause of P20EE.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.