

## RCA-78-24-001-1: Replace Interior Audio Amplifier

Rivian is initiating a customer satisfaction campaign for some model year 2022-2024 R1T and R1S vehicles that may have been built with the incorrect interior audio amplifier. On these vehicles, a firmware update may cause the audio system to stop working. Rivian will replace the interior audio amplifier. Rivian is launching this campaign for customer satisfaction and to ensure the quality of Rivian vehicles.

Document Type	Customer Satisfaction Campaign Bulletin	
Date	September 20, 2024	
Affected Region(s)	USA	
Affected Model(s)	R1T, R1S	
Model Year(s)	2022-2024	
Approximate Build Dates  Pefer to Open Centainments in Service OS to	May 2022-March 2024	
Refer to <b>Open Containments</b> in ServiceOS to determine if this document applies to a specific vehicle.		
Vehicle System	78 - Low Voltage Electrical	
Minimum Service Location	Mobile	

## **Required Parts**

Part Number	Quantity	Engineering Name	Service Name/Notes	
R1T				
PT00000601-G	1	AMPLIFIER_PREMIUM	Amplifier, Audio, Interior	
R1S				
PT00012023-F	1	AMPLIFIER_PREMIUM	Amplifier, Audio, Interior	



**Attention:** The parts listed in this table are only for unique steps that are called out in this bulletin. Some sections of this bulletin might refer to Service Manual procedures which require additional parts. Always review the bulletin and all potentially related Service Manual procedures before ordering parts and beginning work.

## Procedure

- 1. Replace: Amplifier, Audio, Interior (refer to service manual procedure 784210010).
- 2. Reinstall all components that were removed for access and replace all non-reusable components. Refer to the service manual procedures referenced in this document for additional component reusability information and torque specifications.



Labor Code	Description	
RCA782400100	RCA-78-24-001 not applicable	
RCA782400101	Replace interior audio amplifier	
Contact ServiceDocumentFeedback@rivian.com		

regarding labor codes and document content.