

Preview Solution CBR-407-7


Mack Chassis - Correcting The (ABS) MID 136 SID 66 FMI 7 Fault Code

Published 13 September 2024

Valid for all Mack models with equipped with ABS

To correct the MID136 SID 66 FMI 7 fault code the latest Bendix VCP file will need to be downloaded.

From TDP (Trucks Dealer Portal) Click on the Information Tab - Service - Software Downloads - Bendix VCP, install it on the Tech Tool laptop and then reprogram the ABS ECU.



Software Downloads

Downloads & Links:

[TeamViewer - Remote Connection](#) - allow your retail support agent to connect to your desktop in order to assist you

[RollTek Seat Service Software](#)

[Sun Java Runtime Environment](#) - used for Java applications

Workshop Toolbox Downloads:

[Workshop Toolbox Installer](#) – Workshop Toolbox (WT) core application installer

Dealers submit access requests via their Dealer System Administrator who will request in North America Business Partner Master for the specific WT application(s).

PTT Downloads:

[Premium Tech Tool Website](#)

[Tech Tool Installer](#) – Tech Tool Installation Application (Tech Tool Install Instructions included in the zip file). Dealer System Administrator must submit request for User ID access via North America Business Partner, if needed. For Client ID requests, please fill out the form under Forms/Service/Premium Tech Tool Client ID Request.

[Bendix VCP \(v3.0.51\) – November 10, 2023](#)

(VCP Installation Instructions are included in the zipped file that you will download.)

[Dearborn Adapter Drivers](#)

[Nexiq Driver Support](#)

[Noregon DLA 2.0](#)

[Noregon DLA 2.0 Wireless](#)

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article