



active, repair of the harness, and second test drive to verify repair. Use recommended repair code **27-010B**.

- For extraordinary circumstances, file a long form claim and input **27-010** into the "Campaign Code" field.
- Cross-division repairs are not allowed for this campaign.

**Take off parts disposition:** N/A

PRWS CLAIM CODING			
<b>Campaign Code:</b>	27-010	<b>Campaign Type:</b>	Field Repair
<b>Claim Category:</b>	Truck	<b>Repair Type:</b>	Fix-As-Fail
<b>Customer Concern Code:</b>	010	<b>Causal Code:</b>	77
<b>Corrective Action Code:</b>	19	<b>Responsibility Code:</b>	FIXASFAIL
<b>Failure Location:</b>	026-015-007	<b>Causal Part:</b>	E92-6077-2412
<b>Supplier Code:</b>	N/A	<b>SRT Code:</b>	<p><b>B24-44A, 0.7 hr</b> Bulletin 27-010 Inspection, includes test drive.</p> <p><b>B24-44B, 1.8 hr</b> Bulletin 27-010 Inspection and repair per bulletin procedure. Includes two test drives.</p>

Parts

No parts required.

Procedure

Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and

maintained.

Review Links section for repair procedures.

## Attachments

---

[27-010 Procedure Allison Transmission P0848-00 Fluid Pressure Switch Fix](#)