

OWNER NOTIFIED PROGRAM N913 – LOADSPACE FLOOR TRAY

OWNER NOTIFIED PROGRAM N913 - LOADSPACE FLOOR TRAY	
AFFECTED MODELS	24MY Defender 90 and 130 models ONLY
VOLUME AFFECTED	914 US 14 CAN
REPAIR	A concern has been identified on certain 2024 model year Defender 90 and 130 vehicles where the loadspace floor tray was specified but not supplied. Thus, a loadspace floor tray is needed.
REPAIR TIME	0.1 hrs. + DIDO
CAMPAIGN LAUNCH	Launched on September 11th, 2024
NOTES	Retailers should check the warranty portal to confirm affected VIN and following the bulletin service procedure, repair the vehicles at the next service visit.