

POWERTRAIN

NC11 ENGINE NOISE

Range Rover

- 24MY Range Rover
- 24MY Range Rover Sport

Customer Voice:

- An engine whining noise can be heard from within the passenger compartment which increases and decreases with engine speed.

Technical Description:

- Suspected engine oil cooler hose clash.

Action:

- Do not renew any components for this concern.
- Record a video of the whining noise from within the passenger compartment.
- Raise a Technical Assistance (TA) directed to PTS_100 if further assistance is needed and attach the video recording to the TA.
- If no assistance is needed and you have rectified the concern, please open an EPQR with details of your repair.
- There are two audio visual examples in the SSM.



SSM 76156