

WIND NOISE WHILE DRIVING

Customer Voice:

- A customer may complain of a wind noise while driving in the A-pillar/ door mirror area.

Technical Description:

- This may be caused by airflow movement over slight gaps in body trims or seals.

Status:

- TSB JLRTB02120NAS3 has been rescinded with immediate effect.
- More complete and thorough diagnostic work flows have been added to TOPIx Cloud and available through 'Fault and Breakdown' through any of the following symptoms:
 - Body – Glass, Frames and Mechanisms –Rear Quarter Window – Wind Noise
 - Body – Trim and Ornamentation – Exterior – Wind Noise
 - Body – Glass, Frames and Mechanisms – Door Window Glass – Wind Noise
 - Body – Trim and Ornamentation – Exterior – Wind Noise From A-Pillar Area

Range Rover

- 23 - 25MY Range Rover
- 23 - 25MY RR Sport

