

Door Symptom - Noise Complaints from the Door Trim Panel Area: Observe Documentation Specifications (SY 68/22)

Change overview:

Version	Date	Change
1	06/26/2022	<ul style="list-style-type: none"> • First publication
2	08/05/2022	<ul style="list-style-type: none"> • Addition of Taycan
3	08/19/2024	<ul style="list-style-type: none"> • Addition of order types • Split into two documents for 911 and Taycan

Model Line: **Taycan (Y1A / Y1B / Y1C)**

Model Year: **As of 2020**

Cause: The case documentation in the warranty claim does not often clearly indicate the cause and details of the corrective measures carried out in the event of noises in the door and door trim panel.

In order to allow fault correction measures at the factory, fault sources such as loose components or noises must be set:

- Line / train
- Electric plug connections
- Handle
- Cover
- Moulding
- Actuating lever
- Switch
- Material contact point
- Screw connections
- Clips, etc.

must be clearly documented.

The resultant remedial action, e.g.:

- Felt / foam fitted
- greased
- clip replaced
- Screw tightened
- part replaced, etc.

must also be clearly documented.

In the future, for this purpose, the source of the fault in the relevant illustration, inner door trim panel
 ⇒ *View of front inner door trim panel* / ⇒ *View of rear inner rear door trim panel*, outer door trim panel


⇒ *View of front outer door trim panel / ⇒ View of rear outer rear door trim panel* or door without door trim panel ⇒ *View of front door without door trim panel / ⇒ View of rear door without door trim panel*, must be marked and provided with a detailed description of the fault source and corrective measure in accordance with the warranty claim.

**Information**


The warranty claim can only be reimbursed if all documents submitted are complete and comprehensible.

Sample documentation:


- Electric line in the door trim panel loose. Electric line secured with a tie-wrap. For exact fault location, see Appendix xy ⇒ *Appendix xy: Loose cable for door trim panel*



Appendix xy: Loose cable for door trim panel




View of front inner door trim panel



View of front outer door trim panel



View of front door without door trim panel



View of rear inner rear door trim panel



View of rear outer rear door trim panel



View of rear door without door trim panel

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2024 Porsche Cars North America, Inc.