

WRN1 Stop Delivery - Check final drive (rear axle) and replace if necessary

Update 9/13/24

Please be advised that the check is now available for vehicles affected by WRN1. If a vehicle should fail the check, please send a PRMS Warranty / Campaigns ticket to PCNA_Warranty_Support. We will follow up in the ticket with parts and repair information.

We expect less than 10 vehicles to fail the check.

The TI is available in PCSS and the [AfterSales Document Database](#).

WRN1 Stop Delivery - Check final drive (rear axle) and replace if necessary

ID Number	WRN1
Models	Macan (XAB)
Model Years	2024
VIN List	Attached below
Number of affected vehicles	475
Issue Description	<p>There is a possibility that a rear axle final drive was installed on the affected vehicles that does not meet the required specifications.</p> <p>In this case, damage to the rear axle final drive and subsequent mechanical noises and loss of drive to the rear axle cannot be ruled out during dynamic driving.</p> <p>For this reason, the rear axle final drive must be checked before delivery to the customer and, depending on the test result, the final drive maybe replaced.</p> <p>The forecasted failure rate is only 1%.</p>

WRN1 Stop Delivery - Check final drive (rear axle) and replace if necessary

What should Porsche Centers do?

Please ensure that this measure will be carried out on the affected vehicles before the vehicle will be delivered to the customer.

The remedy is now available as of 9/13/24.

TI Number

No. 131-24

Attachments

1. [VIN_List_Report_WRN1_2024-09-09_V2.xlsx](#)