

WRP6 Stop Delivery - Replacing electric power distributor control unit (J1282)

Update 9/17/24

Please be advised that the necessary bolts required to complete WRP6 repairs have not yet been shipped. PCNA will ship these parts tomorrow. If your PC would like to perform the repair without removing these bolts (which are 1 time use only), there is a "Temporary Fix" TI that is posted below. This TI allows for the replacement of the Control Unit without removal of the bolts. The TI will be removed from this post on Friday morning as all hardware will have arrived by that point.

Please note that an error may occur when programming the electrical power distributor control unit.

A solution is currently being worked on at full speed and is expected to be available starting next week.

If an error occurs, please use the workaround attached below to avoid this error until it the solution is available.

As soon as the new PIWIS tester release with the solution is available, we will inform you again via PPN update.

Update 9/16/24 - Repair Launch

Please be advised that repairs can now be completed on vehicles affected by WRP6. Parts have been allocated to Porsche Centers for KF launch vehicles. Please refrain from placing PPL orders or PRMS tickets for parts. All parts will be allocation only at this time.

The TI is available in PCSS and the [AfterSales Document Database](#).

WRP6 Stop Delivery - Replacing electric power distributor control unit (J1282)

ID Number	WRP6
Models	Macan (XAB)
Model Years	2024-2025
VIN List	Attached below

WRP6 Stop Delivery - Replacing electric power distributor control unit (J1282)

Number of Affected vehicles	2,299
Issue Description	<p>Due to an insufficiently configured protective diode at the electric power distributor control unit, an internal failure of the control unit will be diagnosed sporadically.</p> <p>As a result, the control unit stays awake and drains the 12V battery.</p> <p>For this reason, the vehicles may only be delivered to the customer after the electric power distributor control unit has been replaced by an optimized version.</p>
What should Porsche Centers do?	<p>Please arrange for this action to be carried out prior to customer delivery.</p> <p>The remedy is now available as of 9/16/24.</p>
TI Number	No. 153-24

Attachments

- [1. Temporary Fix XAB 2 153-24 WRP6 – Replacing Electric Power Distributor Control Unit \(J1282\) \(Stop Delivery\)_Updt.pdf](#)
- [2. V2 WPR6_Workaround USA 9.17.24.pdf](#)
- [3. VIN_List_Report_WRP6_2024-09-19_V2.xlsx](#)