

WRQ1 Stop Delivery - Replacing spreader device (actuator)

WRQ1 Stop Delivery - Replacing spreader device (actuator)

ID Number	WRQ1
Model Type	718 Boxster / 718 Cayman (982) Panamera (YAA)
Model Year	2024 - 2025
VIN List	Attached
Number of Affected VINs	119
Issue Description	<p>There is a possibility that the spreader device (actuator) for the electric parking brake (EPB) does not meet the required specifications on the affected vehicles. If this is the case, functional restrictions can occur on using the electric parking brake.</p> <p>To prevent this from happening, the spreader device (actuator) on the affected vehicles must be replaced with a spreader device that meets the required specifications</p>
What Dealers Should Do	<p>Please arrange for this action to be taken on the affected vehicles before the vehicles are handed over to customers.</p> <p>The repair is now available as of 9/19/24.</p>
TI	No. 159-24

Required parts

Part number	Designation	Quantity/vehicle	Scope	Ordering Instructions
298609403	Spreader device (actuator)	1 pc(s)	1-4	Order as normal via PPL

WRQ1 Stop Delivery - Replacing spreader device (actuator)

9A700704400	Fit bolt	2 pc(s)	1-4	Order as normal via PPL
N 10456004	Internal hexagon socket round countersunk screw	2 pc(s)	3-4	Order as normal via PPL
PAF009830	Internal hexagon socket round countersunk screw	2 pc(s)	1-2	Order as normal via PPL
99907340201	Cheese head bolt (M12 x 1.5 x 72)	2 pc(s)	1	Order as normal via PPL
9A700758500	Cheese head bolt (M12 x 1.5 x 85)	2 pc(s)	2-4	Order as normal via PPL

Warranty processing

Scope 1:

Damage Code	WRQ1 66 000
Repair Code	2
Labor time	140 TU

Scope 2:

Damage Code	WRQ1 66 000
Repair Code	2
Labor time	140 TU

Scope 3:

Damage Code	WRQ1 66 000
Repair Code	2
Labor time	142 TU

Scope 4:

Damage Code	WRQ1 66 000
Repair Code	2
Labor time	125 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

- [1. WRQ1 Stop Delivery VIN List V2 09.17.2024 HT.xlsx](#)