

WRP7 Stop Delivery - Replacing adhesive strip for the sensor of electric power supply flap left and right

Update 9/16/24 - Repair Launch

Please be advised that repairs can now be completed on vehicles affected by WRP7. Parts have been allocated to Porsche Centers for KF launch vehicles. Please refrain from placing PPL orders or PRMS tickets for parts. All parts will be allocation only at this time.

The TI is available in PCSS and the [AfterSales Document Database](#).

WRP7 Stop Delivery - Replacing adhesive strip for the sensor of electric power supply flap left and right

ID Number	WRP7
Models	Macan (XAB)
Model Years	2024-2025
VIN List	Attached below
Number of Affected vehicles	1,561
Issue Description	<p>Due to unfavorable production tolerances of the electric power supply flap there is the possibility, that a hand gesture for opening the flap is not recognized sporadically.</p> <p>Therefore, the sensor for the left and right electric power supply flap must be removed and installed again with an optimized adhesive strip to compensate for the tolerances.</p>
What should Porsche Centers do?	<p>Please arrange for this measure to be carried out prior to delivery of the vehicle to customers.</p> <p>The remedy is now available as of 9/16/24.</p>

WRP7 Stop Delivery - Replacing adhesive strip for the sensor of electric power supply flap left and right

Please do not order parts. All parts will be allocation only at this time.

TI Number

[No. 156-24](#)

Attachments

1. [VIN_List_Report_WRP7_2024-09-09_V2.xlsx](#)