

WRN2 Stop Delivery - Checking parking lock and replacing drive unit if necessary

Update 9/13/24

Please be advised that the check is now available for vehicles affected by WRN2. If a vehicle should fail the check, please send a PRMS Warranty / Campaigns ticket to PCNA_Warranty_Support. We will follow up in the ticket with parts and repair information.

We expect less than 10 vehicles to fail the check.

The TI is available in PCSS and the [AfterSales Document Database](#).

WRN2 Stop Delivery - Checking parking lock and replacing drive unit if necessary

ID Number	WRN2
Models	Macan Turbo (XAB)
Model Years	2024
VIN List	Attached below
Number of Affected vehicles	386
Issue Description	<p>On the affected vehicles, there is a possibility that the parking lock on the drive unit was not manufactured in accordance with the specifications.</p> <p>In this case, the drive and wheels may not be locked as intended when the Park button 'P' is engaged.</p> <p>For this reason, the parking lock on the affected vehicles must be checked and the drive unit replaced if necessary, before delivery to the customer.</p> <p>The projected failure rate is only 1%.</p>
What should Porsche Centers do?	<p>Please ensure that this measure will be carried out on the affected vehicles before the vehicle is delivered to the customer.</p>

WRN2 Stop Delivery - Checking parking lock and replacing drive unit if necessary

The remedy is now available as of 9/13/24.

TI Number

[No. 132-24](#)

Attachments

1. [VIN_List_Report_WRN2_2024-09-09_V2.xlsx](#)